



Tip	K	I	O	S	d	L ₁	L ₂	L ₃	L ₅	L ₆
03	G ½" RH	G ½"	G ½"	G ⅛" RH	12	30	90	15	125	135
04	G ½" LH	G ½"	G ½"	G ⅛" LH	12	30	90	15	125	135
05	G ¾" RH	G ¾"	G ½"	G ¼" RH	16	30	95	32	140	155
06	G ¾" LH	G ¾"	G ½"	G ¼" LH	16	30	95	32	140	155
07	G 1" RH	G ¾"	G ½"	G ⅜" RH	20	33	103	26	145	160
08	G 1" LH	G ¾"	G ½"	G ⅜" LH	20	33	103	26	145	160
09	G 1 ¼" RH	G 1 ¼"	G ½"	G ½" RH	30	42	128	32	182	196
10	G 1 ¼" LH	G 1 ¼"	G ½"	G ½" LH	30	42	128	32	182	196
11	G 1 ½" RH	G 1 ½"	G ¾"	G ¾" RH	36	40	130	36	185	210
12	G 1 ½" LH	G 1 ½"	G ¾"	G ¾" LH	36	40	130	36	185	210
13	G 2" RH	G 1 ½"	G 1"	G 1" RH	48	60	182	46	255	278
14	G 2" LH	G 1 ½"	G 1"	G 1" LH	48	60	182	46	255	278
15	G 2 ½" RH	G 2"	G 1 ¼"	G 1 ¼" RH	62	68	211	50	295	325
16	G 2 ½" LH	G 2"	G 1 ¼"	G 1 ¼" LH	62	68	211	50	295	325
17	G 3" RH	G 2 ½"	G 1 ½"	G 1 ½" RH	75	90	231	50	286	353
18	G 3" LH	G 2 ½"	G 1 ½"	G 1 ½" LH	75	90	231	50	286	353