



TIP	K	M	d	L ₁	L ₂	L ₄
01	G 3/8" RH	G 3/8"	8	30	90	105
02	G 3/8" LH	G 3/8"	8	30	90	105
03	G 1/2" RH	G 1/2"	12	30	90	105
04	G 1/2" LH	G 1/2"	12	30	90	105
05	G 3/4" RH	G 3/4"	16	30	95	115
06	G 3/4" LH	G 3/4"	16	30	95	115
07	G 1" RH	G 1"	20	33	103	125
08	G 1" LH	G 1"	20	33	103	125
09	G 1 1/4" RH	G 1 1/4"	30	42	128	156
10	G 1 1/4" LH	G 1 1/4"	30	42	128	156
11	G 1 1/2" RH	G 1 1/2"	36	40	130	160
12	G 1 1/2" LH	G 1 1/2"	36	40	130	160
13	G 2" RH	G 2"	48	60	182	220
14	G 2" LH	G 2"	48	60	182	220
15	G 2 1/2" RH	G 2 1/2"	62	68	211	256
16	G 2 1/2" LH	G 2 1/2"	62	68	211	256
17	G 3" RH	G 3"	75	90	231	286
18	G 3" LH	G 3"	75	90	231	286